

## TESTING REPORT

Test Time: <u>2020.12.07</u>

Mode Seat			Tastina Otu	1,000	N.4.	_+!	A1.0001
		post	Testing Qty 1pcs		IVI	aterial	AL6061
Model No.	MSF	P-D604 (M10)	Ф <b>31.6*400</b> mm	n Test Reference		ISO 4210	
Mark		Testing Standard			Testing Result		
Dynamic Test ISO 4210:2014-9 4.5.2		1.The seat post being introduced at a minimal depth in a fitting and being rigidly tightened.  2.The angle between the horizon and choking appliance to elevation 10°  3.The seat post is alternatively under pressure during 100000cycle times.  4.The frequency must not be over 10HZ,F=1200N.  5.During the test no visible break or crack Occur.					
Remark:.  1. Test Reference 2014		nce: ISO 4210-9	ACHINERY (4)	Result NG		PASS	
				Checked by		Tester	
			检测章	3014	2	-	64
MACIV PRECICE MACHINERY/// INCLIAN) COLLED							